

Procedures:

1. Click “setup” to install the software.
2. USB driver installation: First, connecting PC and KORAD POWER SUPPLY through USB cable; then switching on KORAD POWER SUPPLY and the system will pop up new hardware installation window; at this time please select the the drive path of USB driver that KORAD provides, click NEXT, and then the USB drive will be installed on the system. After installation, the port hardware tips of Nuvoton Virtual Com prot(comx) can be seen in the port of the Computer Managerment Window(see the figure 1 below).



Figure 1: The port hardware tips of Nuvoton Virtual Com prot(comx) after the driver is installed succedssfully.